


Note :- DDO on all subs

Detail of auxiliary switchgear at Berwick Substation.

LINE FUSE RATING	
118	40 amp



This Feeder CB Has Autoreclose Fitted

Continued on Page BK1B

REVISION	X	Y	Z	AA	AB	AC	T	U	V	W	DRAWN	I G P	03/89
COMP. NO	-	CFR 12194	-	-	-	-	-	-	-	-	TRACED	T J A	10/06
DATE	07/21	08/22	02/24	01/25	07/25	11/25	10/08	11/09	04/11	04/11	CHECKED		
CHECKED	NH	MB	NH	TJD	LMW	DCH	SJM	SJM	SJM		DES.ENG		



BERWICK No1 6.6kV FEEDER

DATE ISSUED
05/11/25

PAGE
BK 1A