

Note :- DDO on all subs

(FI) :- Earth Fault Indicator


(UTL) :- UTL Dialer

LINE FUSE RATING	

SW 1192
L.B.

This Feeder CB Has Autoreclose Fitted

This Feeder Has 2 Line Autoreclosers Fitted



REVISION	V	W	X	Y	Z	AA	AB	AC	T	U	DRAWN	I G P	05/80
COMP. NO	-	CFR 11248	CFR 12343	-	CFR 12480	-	-	-	CFR 10693	CFR11248 PARTIAL	TRACED	T J A	05/06
DATE	10/21	04/23	11/23	03/24	06/24	09/24	04/25	07/25	04/21	09/21	CHECKED		
CHECKED	NH	MB	NWH	MB	TJA	TJA	MB	MB	NH	NH	DES.ENG		



PORT CHALMERS No3 11kV FEEDER

DATE ISSUED
09/07/25

PAGE
**PC
3C**