




Note :- Tie switch shown thus  is between feeders which cannot be paralleled.



REVISION	L	M	N		E	F	G	H	I	J	K	DRAWN	G I	10/75
COMP. NO	-	SS OFFLOAD	SS RETURN		1886	-	CFR 2378	-	CFR 3994	CFR 6218	CFR 7394	TRACED	T J A	10/06
DATE	05/23	07/24	07/25		11/98	07/01	01/05	10/06	01/09	01/09	11/14	CHECKED		
CHECKED	NH	AC	MGB		KTB	KTB	DLP	SJM	SJM	RWO	SJM	DES.ENG		



SMITH ST No5 6.6kV FEEDER

DATE ISSUED
27/04/25

PAGE
**SS
55**